

Another Solution from

Feb. 2019

ROCKFORD

DRIVE LINE

Can we replace the "Staked-In" u-joint that Jeep used on the 2008-2012 Liberty front shaft?
Yes!! We have the parts to fix that!!!



The factory original front driveshafts found on Jeep Liberty 3.7L models from 2008-2012 has a non-replaceable staked-in style u-joint. With the Rockford Driveline parts below you are able to cut the Original assembly apart 1/4" below the friction weld and replace the Weld Yoke, Flange Yoke & U-Joint with a servicable 1310 system.

R2-28-12187

Weld Yoke -
3.500" CL to Weld
1.760" Butt Dia.



R2-2-1949

Flange Yoke -
2.558" Male Pilot
3.750" Bolt Circle



K153

1310 Series
U-Joint



**Call Today
For Pricing**

THE SOLUTION COMPANY

"PROVIDING QUALITY, VALUE AND SERVICE FOR OVER 60 YEARS"

RockfordDriveline.com | 815-962-1411