

Now Available
High Speed CV Joint - 362-80



Rockford Driveline offers a money saving solution with their High Speed CV Joint product line. Rockford reduces repair expense by enabling the user to simply change-out the defective CV joint, while maintaining the balance of the OEM high speed CV driveshaft. Rockford Driveline High Speed CV Joints come "fully loaded" and are produced to meet the design requirements of the original equipment manufacturer. The new assembly includes Rockford's super-strength OE designed housing with precision-engineered internal components, as well as the new CV boot, end cap, grease, and hardware needed to do the job right.

362-80 (Front Shaft- Front & Rear CV)
2011-2016 Dodge Durango
2011-2016 Jeep Grand Cherokee

This is a 95mm housing, accepts the larger 10mm bolts and fits onto 24 tooth shafts.

Only have a broken boot? We also have Boot Kits available that includes the boot, boot gasket, end cap, end cap gasket, grease & clamp - **362-21**

THE SOLUTION COMPANY

"PROVIDING QUALITY, VALUE AND SERVICE FOR OVER 70 YEARS"

RockfordDriveline.com / 815-962-1411