

Another Solution from

Feb. 2019


ROCKFORD

DRIVE LINE

Can we replace the "Staked-In" u-joint that Jeep used on the 2005-2006 Grand Cherokee & Commander front shaft?
Yes!! We have the parts to fix that!!!



The factory original front driveshafts found on Jeep Grand Cherokee & Commander models from 2005-2006 have a non-replaceable staked-in style u-joint. With the Rockford Driveline parts below you are able to cut the Original assembly apart 1/8" below the friction weld and replace the Weld Yoke, Flange Yoke & U-Joint with a servicable 1310 system.



**Call Today
For Pricing**

THE SOLUTION COMPANY

"PROVIDING QUALITY, VALUE AND SERVICE FOR OVER 60 YEARS"

RockfordDriveline.com | 815-962-1411